

Enforcement Orders Signed March 24, 2015

Alliant Gas, Docket No. GUD 10371

System #960686/Las Brisas at Ensenada Shores

Rules violated:

Violation No. 1

Requirement: 49 CFR 192.603(b)

Records necessary to administer the operation and maintenance plan were not maintained or were inadequate.

System #961068/Company wide system

Violation No. 1

Requirement: 49 CFR 192.625(f)

To assure proper concentration of odorant, periodic sampling of combustible gases was not conducted using an instrument capable of determining the percentage of gas in air at which the odor becomes readily detectable.

Violation No. 2

Requirement 16, 8.225(b)(2)

Information for new installations of plastic pipe was not being recorded or maintained for each new pipeline segment.

Penalty paid: \$10,000.00