

Enforcement Orders Signed December 5, 2017

Enterprise Crude Pipeline, LLC

Docket No. GUD 10632

System Name: C-1, Hope to Sealy, 8" (System id 552219)

Violation Code: 195-402-500

Written procedures for each pipeline system were not followed as necessary.

Location: Sealy Tank Farm

Comment: The Operator did not follow written procedure (Pig Removal 8").Preparation step # 46, which requires HOV-170,2" valve to be closed was not followed.HOV-170,2" drain valve consequently left open causes the leak to occur.

Rules violated:

49 CFR 195.402

PENALTY PAID: \$5,000.00

Grapevine Estates

Docket No. 10625

System Name: Grapevine Estates Mobile Home Park (System id 661031)

Violation Code: 192-DIM-501

Operator failed to develop a distribution integrity management plan (DIMP) by 08/02/2011.

Comment: Repeat violation from IP# 108688.

Rules violated:

49 CFR 192.1005

PENALTY PAID: \$500