

Enforcement Orders Signed April 23, 2019

GUD 10721

SUNOCO PIPELINE LP

System Name: 10" NEDERLAND TO LONGVIEW

System ID No.: 965206

Violation Code: 195-579-502

Corrosion inhibitors were not used in sufficient quantity to protect the entire part of the pipeline that the inhibitors were designed to protect.

Requirement: 49 CFR 195.579(b)(1)

Violation Notes

<u>Evaluation ID</u>	<u>Violation State</u>	<u>Previous Evaluation ID</u>	<u>Location</u>	<u>Note</u>
20173335	Uncorrected		Thomas Station GPS: 32.47849, -94.86813	The operator batch treats the entire system with Biocides in conjunction with corrosion inhibitors to mitigate internal corrosion. The operator determined the root cause of the leak was due to internal corrosion therefore the amount of inhibitor was not sufficient to protect the entire system.

Penalty collected: \$3,630.00