

Enforcement Orders Signed April 4, 2017

UAH Property Management

Docket No. GUD 10576

System Name: The Heights on Congress Apt. (System ID #460798)

Item # 1

Violation Code: 16 TAC 8.51 (b) - The master meter operator did not have on file with the Commission an approved organization report Form P-5.

Comment: (FORM P-5) Organization Report-Annually (16B-051-002) In order for an operator ID number to be processed and maintained by the Railroad Commission of Texas (RRC), an Organization Report Form (P-5) must be filed with the RRC-Oil & Gas Division, P-5 Department (512-463-6772). Master Meter Operators are required to submit an annual fee of \$562.50. Once the fee and Form P-5 has been processed by the P-5 Department, an Operator ID number will be assigned to the Master Meter Operator. The operator will receive a statement by the RRC referencing their Organization Report/Operator ID number has been processed. The referenced P-5 Organization Form and instructions were provided during this safety evaluation. Once your Organization Report (P-5) number has been assigned, please reference the assigned P-5 number within your confirmation letter back to the RRC Pipeline Safety Division.

Item #2

Violation Code: 49 CFR 192.1015(a) - he Distribution Integrity Management Plan was not written and implemented per the requirement of 192.1015 by 08/02/2011, OR

For a gas system put into service, or acquired after 08/02/2011, a plan was not written and implemented prior to beginning of operating.

Comment: DIMP Plan was not written and implemented at the time of the inspection.

AGREED ORDER SIGNED: 4/4/17

PENALTY PAID: \$1,100.00