

Enforcement Orders Signed June 21, 2018

Buckeye Texas HUB

Docket No. GUD 10725

System Name:

Alpha 20-1 (System id #963425)

Violation No. 1:

Overpressure controls and protective equipment were not adequate on the listed pipeline(s).

Note: Operator's protective equipment did not adequately control the pressure of the system during a surge event to prevent failure of a component.

Requirement:

49 CFR 195.406(b)

Penalty collected: \$6,000.00