

Enforcement Orders Signed June 4, 2019

GUD 10785

Atmos Energy Corp., Mid-Tex

System Name: HALTOM CITY

System ID No.: 612026

Violation Code: 16E-018-001

The Operator failed to comply with Title 16 of the Texas Administrative Code Chapter 18 Underground Pipeline Damage Prevention.

Requirement: Title 16, 18.1

Violation Notes

<u>Evaluation ID</u>	<u>Violation State</u>	<u>Previous Evaluation ID</u>	<u>Location</u>	<u>Note</u>
20180030	Uncorrected		5547 Bonanza Drive	The operator's contracted line locator failed to follow procedures for covered task M-03 Locating and Marking Lines. The records show that the contracted line locator failed to mark the entire scope of dig ticket #1785622363, including the bore-strike area. The excavator requested marking "begin locating at this intersection going south on Bonanza Dr, marking the front and rear easement on both sides of this road for about 1200 feet." The intersection referenced is Bonanza Drive & Alyse Drive according to the ticket details. Photos taken of the line marks were provided by Contract Locator HTH-2748. None of the photos show line marks at the incident site; the location of the line marks in the photos could not be determined. Results of the operator's & contractor's investigations determined "Incorrect Operations: failed to mark the entire scope of the ticket."

Penalty collected: \$9,000.00