

# Enforcement Orders Signed March 26, 2019

## GUD 10720

### Plains Pipeline LP

System Name: Sundown to CR 660, 8"

System ID No.: 962391

**Violation Code: 195-402-500**

The operator did not prepare and/or follow, for each pipeline system, a manual of written procedures for conducting normal operations and maintenance activities and handling abnormal operations and emergencies.

Requirement: 49 CFR 195.402(a)

**Violation Notes**

<u>Evaluation ID</u>	<u>Violation State</u>	<u>Previous Evaluation ID</u>	<u>Location</u>	<u>Note</u>
20180176	Uncorrected		Sundown Station 33.396743, - 102.409332	195.402(a), failure to follow procedures for monitoring and controlling internal corrosion of idle/dead leg pipelines as described in Spec. No 728 Internal Corrosion-Monitoring Procedure Section 4.0.5. Reference of previous write up can be found in Incident #1450(PID #114308).

**Penalty collected: \$7,000.00**